

## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY SUPERFUND SITE STRATEGY RECOMMENDATION - REGION 06



Site Name: Section 17 Mine - NM0021		CERCLIS ID#: N/A	
Alias Site Name: Jerry Wayne No. 1-36, Ca	rter, Shale No. 1-36	<u> </u>	
Address: Latitude 35 degrees 26'19.11" Long	gitude 107 degrees 49'10.52"		
City/County or Parish/State/Zip: McKin	ley County, New Mexico	· · · · · · · · · · · · · · · · · · ·	
Report Type: Pre-CERCLIS Screening	Date: 10/31/11	Author: NMED	
RECOMMENDATION:		,	
No Further Remedial Action Planned Under Superfund (NFRAP)	☐ PA ☐ SI ☐ ESI ☐ Other		
☐ 3. Action Deferred to: ☐ RCRA ☐ 1 ☐ 4. Site Being Addressed Under the State	NRC BLM	CP): Yes No	
NOTIFY AUTHORITY:		_	
Remedial State/Tribe N	SCA CAA  IPDES NRC  JIC SPCC	SMCRA Resource Trustee: Other:	
Enforcement Facility	ne 🔲 51 ee		
SEND SSSR COPIES TO: 6SF-AC	☐ 6WQ-SP ☐ ATSDE	R State Agency Tribal Agency	
DISCUSSION:			
are located on approximately 22 acres of distu Section 18 and 20.	wet mine and records indicate to ough the mine to further leach turbed surface on Section 17 and	that during mine operations, solution mining uranium). The surface facilities and main shaft the underground workings extend into parts of	
Mine reclamation is being required pursuant to discharge of mine water and solution mining i Commission regulations.			
NMED recommended that no further action be activities pursuant to New Mexico regulations		Section 17 Mine site due to on-going remedial mendation.	
		د د د د د د د د د د د د د د د د	



Page 1 of 2

<b>APPROVALS:</b>			$\bigcirc$ $\mu$	
Report Reviewed by:	Lisa Marie Price (Site Assessment Manager)	Signature:	ise Mary hia	Date: ///29///
Disposition Approved by:	John Meyer (Section Chief 6SF-TR)	Signature:	In hy	Date: 112914